

# Rapport d'essai / Test report

Report : 19/00449

|                                    |                                                                                                        |                           |               |
|------------------------------------|--------------------------------------------------------------------------------------------------------|---------------------------|---------------|
| <b>Applicant</b>                   | Argosy International Inc.<br>Mr BOUCHET Thierry<br>225 W. 34 St Suite 1106<br>10122 New York<br>USA    |                           |               |
| <b>Subject</b>                     | R95 barrier calibration test in dynamic test according to the regulation R95<br>rev: Compl.6 série 03  |                           |               |
| <b>Service / Location of tests</b> | Passive Security Service (SEP)<br>Autodrome of Linas Montlhéry<br>BP20212 – 91311 Montlhéry Cedex      |                           |               |
| <b>Testing date</b>                | 21th January 2019                                                                                      | <b>Internal reference</b> | ARCSAS1900330 |
| <b>Technician</b>                  | Guillaume NIEL                                                                                         |                           |               |
| <b>Summary / Conclusion</b>        | Tests carried out according to the regulation in use.<br><br>Blocks are in tolerance of the corridors. |                           |               |

|                            |                                                                                                            |                                                                                                                        |
|----------------------------|------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|
| <b>Name</b>                | Aurélien GABORIT                                                                                           | Jean-Philippe LEPRETRE                                                                                                 |
| <b>contact information</b> | <a href="mailto:aurelien.gaborit@utacceram.com">aurelien.gaborit@utacceram.com</a><br>+33 (0)1 69 80 17 22 | <a href="mailto:jean-philippe.lepretre@utacceram.com">jean-philippe.lepretre@utacceram.com</a><br>+33 (0)1 69 80 17 32 |
| <b>Functions</b>           | Test Technician                                                                                            | Manager of Passive Safety Service                                                                                      |
| <b>Dated</b>               | 22/01/2019                                                                                                 | 22/01/2019                                                                                                             |
| <b>Signature</b>           |                         |                                   |

NB: The present tests can not in any way engage the responsibility of the UTAC with regard to the industrial or commercial realizations which could result from it. "Reproduction of this document is permitted only in the form of an integral photographic facsimile". The test results only relate to the equipment tested and identified in this test report.

Technical Union of the Automobile, Motorcycle and Cycle  
 Autodrome of Linas-Montlhéry BP20212 - 91311 Montlhéry Cedex France  
 Test Center of Mortefontaine Route du Golf - 60128 Mortefontaine  
 Tel: Montlhéry: +33 (0) 1 69 80 17 00 / Mortefontaine: +33 (0) 3 44 54 51 51

Simplified joint-stock company with a capital of € 7,800,000  
 VAT FR 89 438 725 723- Siren 438 725 723 RCS Evry  
 APE Code 7120 B

